

# Drive System Change

Parts Bulletin: PB-LAD10002



Revision 1

Date:  
11/24/2021

Page 1 of 1

## MODELS:












MLV45N1BWW

MLV45N3BWW

MLV45N1BWWC

**Topic:** To increase durability and reduce noise, the drive system will be changed from a V-Ribbed belt system to a V-Belt system. To accommodate this change additional components will also be updated. To order the correct parts please refer to the serial number and production dates. The change has been made on 11/13/2021 with the below serial numbers and after having the new parts. If your production date and serial number is after 11/13/2021, please select the new part numbers when ordering.

Model Number	Serial Number
MLV45N1BWW	341380007Q11B135M00001
MLV45N3BWW	341380007UW1B125M00001
MLV45N1BWWC	341380007Q11B135M00001

No	Name	Current		NEW	
		P/N	Picture	P/N	Picture
1	Clutch	12938000001941		12938000000354	
2	Insulation pad under motor	12138000002868		12138000002864	
3	Motor pulley	12338000000421		12338000001241	
4	Belt	12638000001161		12638000003042	
5	Insulation pad upper motor	12138000036963		11301002000313	
6	Motor	11002012000022		11002012040074	